





foundation has completely failed



foundation has completely failed



A photograph showing the interior of a wooden structure, likely a basement or crawlspace. The floor is made of wooden planks, some of which are rotten and discolored. A vertical white text box is overlaid on the image, containing the following text:

foundation has completely failed



foundation has completely failed. Showing 6" discrepancies over a 4' span as can be seen with the 4' level exhibit.



foundation buckled.



wall fully rotted

significant lean/slope of floors & walls








rotten floor & sub floor

4" out of level over 4' span.



driveway draining into house



rotten floor & subfloor

**house leaning significantly.
2" over 4' span.**



**house leaning significantly.
3" over 4' span.**





house leaning significantly.
1 1/2" over 4' span.

**significant lean putting doors out of square
to the extent some are buckling.**









foundation 4" off over 4' span



**original back door gone and was
replaced with this metal door.**



**original front door +
window above gone.
Door boarded up to keep
people out.**